

REPORT OF PERIODIC THOROUGH EXAMINATION OF HOIST OR LIFT

as required by the Lifting Operation and Lifting Equipment Regulations 1998;
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: X4L143782

Plant Code: L27AHH

Previous Report: 150717-002-0013PL1

Site: 00001

Schedule: L0001

Report Number: 030418-002-0014PV1

L0L54

Employer (or owner) of premises	DOVE LODGE COMMUNITY RESOURCE CENTRE
Address	49 Beach Road, Littlehampton West Sussex, BN17 5JG
1. (a) Type of hoist or lift and identification number and description	Passenger/Goods Lift Hydraulic
(b) Date of construction or reconstruction (if ascertainable)	Oakland Elevators Serial No.:- 8013 1997
2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?	No
(b) Were examinations in accordance with an examination scheme?	No
3. Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use.	
(a) Enclosure of hoistway or liftway.	Yes
(b) Landing gates and cage gate(s).	Yes
(c) Interlocks on the landing gates and cage gate(s).	Yes
(d) Other gate fastenings.	Yes
(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes
(f) Over-running devices.	Yes
(g) Suspension ropes or chains, and their attachments.	N/a
(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Yes - Visual Examination
(j) Brakes.	N/a
(k) Worm or spur gearing.	N/a
(l) Other electrical equipment.	Upper shaft light should be returned to service.
(m) Other parts.	No - An approved warning notice should be fitted to motor room door.
4. What parts (if any) were inaccessible?	All concealed parts
5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-	
(a) defects found which give rise to imminent danger and require attention immediately.	None
(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None
6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	630 kg/8 Persons
7. Other observations	See Plant Report Continuation

This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 14 Mar 2018

Date of Last Examination: ---

Inspecting Engineer: Mr J Saldanha

Date of Next Examination: 14 Sep 2018

Signature:



Qualification: Engineer Surveyor

PLANT REPORT CONTINUATION



HSB Engineering Insurance

Policy: X4J143782

Plant Code: L27AHH

Previous Report: 150717-002-0013PL1-C01

Site : 00001

Schedule: L0001

Report Number : 030418-002-0014PV1

Occupier DOVE LODGE COMMUNITY RESOURCE CENTRE

Address 49 Beach Road, Littlehampton
West Sussex, BN17 5JG

PRC1

Section	Remarks
7	Lift motor room should not be used as a store room. Last service 03.08.17 Oil reservoir should be contained in the event of a leak.

Date of Examination: 14 Mar 2018

Date of Last Examination: ---

Inspecting Engineer: Mr J Saldanha

Date of Next Examination: 14 Sep 2018

Signature:

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited
Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service

